

Date: **8/14/14**

Engineering Bulletin: **081401**

Effective Date: **8/18/14**

Released By: **Mary Olivier**

Subject: **CVR Rod -P3692C**

First Choice CVR top rods are not fully threaded.

Cutting down top rods is required for doors heights less than 80".

This action does not leave enough threads to attach the top latch and locking nut.

In these cases, manufacturing needs to remove the rods and rethread them.

CVR door heights less than 80" will have an additional fee of \$25 per leaf for this extra handling and threading.

Changing the door height to 80" or above will eliminate the fee.

