

Date: February 22, 2012

Engineering Bulletin: 021202

Effective Date: February 22, 2012

Released By: Jamie Magnusson

Subject: Non Thermal Sill Flashing E14055

Description: Due to design changes, implemented to improve the thermal manufacturing process, we will no longer offer our T14055 sill flashing, in non-thermal form. T14055 is available for a thermal sill flashing and E14059 is available for a non-thermal sill flashing.



